



VDI live tooling

Operation with Star-type Turrets



The orientation of the revolver to the spindle is important. Machines with Star-type Turrets often come with a sub spindle.

Right and Left hand Versions on Star-type Turrets with Main and Sub Spindle



Left hand Version

Please note dimension H

Right hand Version

Please note dimension H

Please check interference circles with fixed tools!

